

17HS043 Quality and Reliability Lab

1. Construction of (\bar{X} , R) charts.
2. Construction of P-chart-Fixed sample size.
3. Construction of P-chart-variable sample size
4. Construction of NP-Chart .
5. Construction of C-Chart.
6. MS-Excel methods for the Serial Numbers 1.
7. MS-Excel methods for the Serial Numbers 2 to 4.